

INSTALLATION INSTRUCTIONS

 ENSURE THE APERTURE IS CLEAN AND FREE OF DEBRIS AND LOOSE CEMENT. REMOVE ALL DUST FROM SURFACES REQUIRING INSTALLATION.

2. SELECT THE TD100 COLLAR. SMALLER DIAMETER TD COLLARS MAY BE USED ON REDUCED SERVICE PENETRATIONS THROUGH THE APERTURE.


 SECURE THE TD COLLAR AROUND THE HVAC SERVICES BUNDLE AND SLIDE IT INTO THE APERTURE. ENSURE FIXING TABS ARE FLUSH WITH THE TOP OF THE CONCRETE FLOOR.

4. SECURE THE TD COLLAR IN POSITION USING 32MM MASONRY SCREWS THROUGH ALL FIXING TABS.

 APPLY RYANFIRE MASTIC TO SMOKE SEAL BETWEEN THE CONCRETE FLOOR AND THE TD COLLAR FROM ABOVE.

6. APPLY RYANFIRE HP-X INTO THE GAP BETWEEN THE COLLAR AND THE MIXED SERVICES.

7. REMOVE ANY EXCESS HP-X WITH A DAMP CLOTH



FLOOR

TD COLLAR SIZE	CORE HOLE DIAMETER
TD 40	Ø72mm
TD 50	Ø82mm
TD 65	Ø102mm
TD 80	Ø112mm
TD 100	Ø142mm

All errors and omissions excepted. The information contained within this drawing is believed to be correct on the date of publication, and is based upon tested and certified solutions. The policy of Ryanfire Products is one of constant improvement. Installers must ensure that they are following the latest published drawings, test evidence and instructions. Whilst Ryanfire Products will endeavour to keep its publications up to date, the accuracy of the information contained within this drawing may be affected by pertinent changes in the law or regulatory requirements and alterations or amendments to the specification of the manufactured products. Terms and conditions of sale apply.

Ryanfire Products owns and has copyright to these drawings. They are to be used only for the purpose for which they were intended and supplied and are not to be sold, transferred or made available for use by a third party. Any misuse of these drawings will result in legal proceedings.

EXTENDABLE TABS

Web based drawings are for example only. Fire performance of any system is dependant on, but not limited to size of opening, substrate, if penetrations are passing through, type, size and number. Please refer to Ryanfire technical department for detailed and specific fire performance information.



RYANFIRE Technical Support: info@ryanfire.co.nz - Tel 09 443 0362

Drawing Title

Products:

Approvals: BK: Ref:

Scenario:

Services:

Construction:

Fire Integrity: 120 minutes

Fire Insulation: 60 minutes

ID:

RYANFIRE TD COLLAR RYANFIRE HP-X RYANFIRE MASTIC

AS 1530.4/AS 4072.1

(heat pump services)

Penetration seal to HVAC bundle

3 sets pair coil copper pipes

100mm thick concrete floor

FRT 190287

Up to:

6 TPS cables Ø25mm uPVC pipe

TD Collar to HVAC bundle 100mm concrete floor

NTS July 2024

Drawing Number Rev

V17.11

9.0